



NAVAJO WESTERN WATER DISTRICT
705 Navajo Road; Walsenburg, CO 81089
Telephone: 719-738-3130 / Email: operator@nwwd.us

NAVAJO WESTERN WATER DISTRICT
OPERATIONS REPORT FOR March 2024

Water Pumped: Resorts, 579,524 Estates, 144,434 = 723,958 gallons.
Through 03/29/2024

Usage by Customers: 663,663 = Loss of (60,295) 8.3% Loss

Work Accomplished:

- 1. Passed Monthly Coliform Test.**
 - 2. operators Exam passed. Contact information updated.**
 - 3. All tank sites and pump houses cleaned and inspected.**
 - 4. Water Heater Fixed. La Veta Propane.**
 - 5. Emergency Response and Standard operating procedures continued.**
 - 6. Assist customers with leaks. (23 Deer Trail).**
 - 7. Sanitary Survey.**
- Tank 2A Screens replaced and all metal tape removed from tanks. Pictures submitted with state to verify gasket quality.**
 - Well head gaskets installed.**
 - Periodic tank inspections (Filled out but not dated. Not accepted by state).**
 - Comprehensive Poly tank inspections (completed and submitted, informed both state auditors of meeting with tom for tank draining procedure. Another comprehensive inspection will follow including pictures of inside of tanks)**
 - Storage tank finished water rule.**
 - Metal tank comprehensive inspections (Found, dated Apr. 2021, Due in Apr 2025) Submitted to file cabinet.**
 - Emergency Response pressure loss.**
 - Emergency response S.O.P for Chlorine solution barrel becoming clogged.**
 - monitoring plan updated for both resorts and estates.**

Requests: Articles

Thank You All!

Dave Rabideau ORC

Presented e April 11, 2024 BOD mtg